

WHAT'S IN THE BOX?

WHY DO YOU NEED 3-PHASE PROTECTION?

If it's the ICM450A & the ICM530 or the ICM450A+ PLUS and the ICM531, whichever combo you choose, know that you are getting the protection you need.

- Phase loss and phase imbalance can quickly burn up a motor creating costly repairs
- Phase reversal can tear up a scroll compressor and cause other irreputable damage
- Fast acting transient surges can damage sensitive electronic control boards and destroy the ICM450A/450A+ voltage monitor as well
- Four combos to choose from



Which Protection Bundle do I need?

Models	Three-Phase Voltage
ICM530 + ICM450A or ICM450A+	240 VAC Delta / Wye
ICM531 + ICM450A or ICM450A+	480 VAC Delta / Wye